- Site Service Report -

Date:June 10, 2009

IRD SO.:10785I IRD Contract No.:10785I

From: Brent Eckhart To:Sheri Perrett
Project Name/Location: Danville LTTP/Danville, VA RT. 29 SB

Service Date(s):May 22, 2007

Job Description: Saskatoon head office has contacted me May 16, 2007 and asked me to provide a

technician to travel to Danville LTTP site to replace a card and provide any assistance

locally that head office techs might required.

Work Completed:

- Travelled to Danville.
- Contacted Ian Meyers in head office prior to my arrival and informed him that I would be onsite. He told me to replace the sensor interface card once on site and then call him
- I replaced the card upon arrival. The sensor interface card appeared to work immediately upon installation.
- I called lan back. He dialed in, confirmed that the card was working properly and that the proper firmware had been installed. He told me I was no longer needed on site.
- I gave the cabinet a quick inspection. All connections were tight and cabinet was very clean.

Work Remaining:

Parts Used: one SSM card card, P/N 195210

Mileage / Travel Time:

- 3 hour travel to site
- 3 hour return trip
- 1 hour total on site labor

Notes:

Action Items:

| Item | Action Required | Ownership |
|------|-----------------|-----------|
| 1. | | |



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East, Saskatoon, SK, Canada, Phone: (306) 653-6600 Fax: (306) 242-5599

| 2. | |
|----|--|
| 3. | |
| 4. | |

6/19/96 IRD FORM No.: <u>1304A</u>